Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	4437	ferrule\$1 with (bore\$1 boring hole\$1) with fib\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/04 17:06
L2	6675	fib\$3 with (bragg near3 grating\$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/04 17:06
L3	850	(amp amplif\$5) with (bragg near3 grating\$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/04 17:06
L4	0	L1 and L2 and L3 and @pd>"20050328"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/04 17:06
L5	202	(fib\$3 with (bragg near3 grating\$1)) same (uncover\$4 protrud\$4 groov\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/04 17:07
L6	0	L5 and L1 and L3 and @pd>"20040328"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/04 17:07
L9	913	(fib\$3 with (bragg near3 grating\$1)) same (uncover\$4 protrud\$4 expos\$4 groov\$3)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/04 17:07
L10	4	L9 same stress and @pd>"20050328"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/04 17:08

L13	4437	ferrule\$1 with (bore\$1 hole\$1) with fib\$3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT;	OR	OFF	2006/01/04 17:08
L14	6341	ferrule\$1 with (cut\$4 groove\$1 incis\$5 slic\$4)	IBM_TDB  US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/04 17:08
L15	1066	L13 and L14	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/04 17:08
L16	742	L15 and (ferrule\$1 with groove\$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/04 17:08
L17	7	L16 and @ad<"20020925" and @pd>"20050401"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/01/04 17:09